


Tool for flexible assembly to Barb. Fitting

T Handle



Use M10
x 50 Bolt.

